

Chief, Services Division

27 November 1950

25X1A9a  
FOIAb3b1

Attn: [REDACTED]

Chief, [REDACTED]

**Installation of Shelves for Rectifier Unit and Key Box**

FOIAb3b1

1. The rectifier unit and key box now used by [REDACTED] in its Wire Room (Room 334 South Building) requires use of two shelves for wall mounting. Similar shelf facilities must be installed in Room A, [REDACTED] as per attached drawing. Work must be completed prior to move of the [REDACTED] Wire Room to that location.

25X1A6a

FOIAb3b1

FOIAb3b1

25X1A6a

2. To save time and materials the rectifier unit and key box in Room 334 South Building may be placed on the floor until [REDACTED] is moved, thus permitting the shelves to be dismantled and reinstalled in Room A, [REDACTED]

FOIAb3b1  
25X1A9a

3. It is requested that this work be performed prior to 1 December 1950. [REDACTED] Chief Engineer, [REDACTED] Extension 2915, may be contacted for details of this installation.

25X1A9a

**Attachment**

JRC:pod

cc: Addressee - Orig & 2

25X1A9a

[REDACTED] - 1

[REDACTED] - 2

Adm. Off. - 1

25X1A9a

[REDACTED] - 1

Document No. 148  
No Change in Class. ☒  
☐ Declassified  
Class. Change: [REDACTED]  
Rev. History: [REDACTED]  
Auth: [REDACTED]  
Date: 5-30-79 37 [REDACTED]

This document part of classified integrated file. NARY check required prior to individual classification action.